	•			,
L	Hits	Search Text	DB	Time stamp
Number		interest firms noon chamber	USPAT;	2003/04/01
1	63	pressure near intensifying near chamber		11:04
			US-PGPUB;	11:04
		•	EPO; JPO;	
			DERWENT	
	0.1	(pressure near intensifying near chamber)	USPAT;	2003/04/01
	21		US-PGPUB;	09:35
	i	and fuel		09.33
		•	EPO; JPO;	
		· ·	DERWENT	
1		//	USPAT;	2003/04/01
3	9	((pressure near intensifying near		09:35
	1	chamber) and fuel) and (check near valve)	US-PGPUB;	09.33
			EPO; JPO;	
	į		DERWENT	
	_	inhandfuing noon	USPAT;	2003/04/01
	8	(((pressure near intensifying near	·	
		chamber) and fuel) and (check near	US-PGPUB;	09:35
		valve)) and plunger	EPO; JPO;	
		varve,, and promise	DERWENT	
			USPAT;	2003/04/01
5	6	((((pressure near intensifying near		
ŀ		chamber) and fuel) and (check near	US-PGPUB;	09:36
1		valve)) and plunger) and needle	EPO; JPO;	1
I		varvo,, and prangon, and	DERWENT	
ļ			USPAT;	2003/04/01
5	6	(((((pressure near intensifying near		
]	1	chamber) and fuel) and (check near	US-PGPUB;	10:57
l		valve)) and plunger) and needle) and	EPO; JPO;	
ļ		drain	DERWENT	
ļ		arain	USPAT;	2003/04/01
7	3	((((((pressure near intensifying near		
•		chamber) and fuel) and (check near	US-PGPUB;	09:43
		valve)) and plunger) and needle) and	EPO; JPO;	
		Junia) and throttle	DERWENT	
1		drain) and throttle	USPAT;	2003/04/01
3 l	3	((((((pressure near intensifying near	· ·	1
•		chamber) and fuel) and (check near	US-PGPUB;	09:44
j		valve)) and plunger) and needle) and	EPO; JPO;	
		drain) and throttle) and intensifying	DERWENT	l
	,	drain) and throttie, and intensitying	USPAT;	2003/04/01
9	3	((((((pressure near intensifying near		09:44
		chamber) and fuel) and (check near	US-PGPUB;	09:44
		valve)) and plunger) and needle) and	EPO; JPO;	
		drain) and throttle) and intensifying and	DERWENT	
		l ·		
l		chamber	USPAT;	2003/04/01
10	5	(((((pressure near intensifying near	1	
	1	chamber) and fuel) and (check near	US-PGPUB;	11:02
±		(valve)) and plunger) and needle) and	EPO; JPO;	Į.
,			DERWENT	
	,	return	USPAT;	2003/04/01
11	3	(((((pressure near intensifying near		· ·
		(chamber) and fuel) and (check near	US-PGPUB;	11:02
		valve)) and plunger) and needle) and	EPO; JPO;	
		valve)) and plunger, and needle,	DERWENT	
	1	(fuel near return)	USPAT;	2003/04/01
12	117306	pressure near chamber		
			US-PGPUB;	11:05
			EPO; JPO;	
	1		DERWENT	\$
	\		USPAT;	2003/04/01
13	9282	high near pressure near chamber	1	
			US-PGPUB;	11:06
	1		EPO; JPO;	
•	1 ;	·	DERWENT	
			USPAT;	2003/04/01
14	316	(high near pressure near chamber) and		`_
• •		(fuel near injector)	US-PGPUB;	11:07
		/====	EPO; JPO;	I .
	1 '		DERWENT	
				2003/04/01
15	. 76	((high near pressure near chamber) and	USPAT;	
10	1	(fuel near injector)) and plunger and	US-PGPUB;	11:07
			EPO; JPO;	1
	l' .	needle		· ·
×.			DERWENT	2002/04/01
16	26	(((high near pressure near chamber) and	USPAT;	2003/04/01
16	20	(fuel near injector)) and plunger and	US-PGPUB;	11:07
	1	(Tuel Hear Injector) and planger and	EPO; JPO;	1
		needle) and drain	DERWENT	
		b.	1 DEKWENT	i